



TECHNICAL BULLETIN

To: Hemisphere GNSS Dealers and End Users
From: Hemisphere GNSS
Date: **November 20, 2017**
Reference #: [TB262017-11-20](#)

PRODUCTS AFFECTED:

- S321 UHF Receiver
- S321 Network Receiver
- C321 UHF Receiver

SCOPE:

HGNSS has released new OSBoot (v4.16_4.03_171116) and WebUI firmware (v1.39.171116) as well as an increase from 4GB to 8GB internal memory for the products listed above. This new firmware release represents Hemisphere GNSS's ongoing commitment to ensure HGNSS customers experience the best possible performance from their products.

The enhancements and improvements available with this new firmware are outlined below:

Firmware Update Notes
OSBoot v4.16_4.03_171116 <ul style="list-style-type: none">• Added support for 8G internal memory.• Modified the configuration of the current network module (cannot be reversed)• Added support PLS8 network module.• Does not allow the firmware to be downgraded to a previous version (to ensure proper network module functionality).

**WebUI v1.39.171116**

- Modified the configuration of the current network module (cannot be reversed)
- Added support PLS8 network module).
- Added ability to upgrade P326's FW.
- Fixed occasional data logging error.
- Does not allow the firmware to be downgraded to a previous version (to ensure proper network module functionality).

Product-specific release notes and binary files can be downloaded on our website at WWW.HGNSS.com/Resources-Support/Software

FURTHER INFORMATION:

If you have any further questions, please contact Hemisphere GNSS technical service department at +1 (480) 348-6380. For support via email, please contact TechSupport@HGNSS.com or consult WWW.HGNSS.COM for the latest HGNSS product and software information.

This document is provided for technical support purposes only.
Please refer to the product documentation for warranty, license and safety information associated with the product.