



TECHNICAL BULLETIN

To: Hemisphere GNSS Dealers and End Users
From: Hemisphere GNSS Technical Support
Date: September 25, 2017
Reference #: TB222017-09-25

PRODUCT AFFECTED:

**Hemisphere GNSS A101 Smart Antenna.
Hemisphere GNSS P102 OEM GPS Receiver**

SCOPE:

HGNSS has released new positioning engine firmware **1.2 Qg24p** for the Crescent P102 OEM module and the A101 smart antenna. This new firmware release is being offered to ensure that HGNSS customer experience the best possible performance from their products. The enhancements and improvements made available with this new firmware are outlined in the below table.

DETAILED INFORMATION:

Update
Improved EGNOS tracking and signal re-acquisition routines
Updated station ID reporting integrity for RD1 message
Updated NMEA RAIM status flag for GPGNS, GLGNS, GAGNS NMEA sentences

FURTHER INFORMATION:

If you have any further questions, please contact Hemisphere GNSS technical service department at +1 (480) 348-6380. For support via email, please contact TechSupport@HGNSS.com or consult WWW.HGNSS.COM for the latest HGNSS product and software information.



This document is provided for technical support purposes only. Please refer to the product documentation for warranty, license and safety information associated with the product.