



TECHNICAL BULLETIN

To: Hemisphere GNSS Customers and End Users
From: Hemisphere GNSS
Date: **July 15, 2019**
Reference #: SB162019-07-15

PRODUCTS AFFECTED:

All Hemisphere GNSS receivers that are configured to track Galileo signals.

SCOPE: Galileo Service Interruption

Please be advised that there is a system advisory currently in place for all Galileo users. It was issued on July 11th, 2019 and does not have specified end date. Observed system behavior shows that the Galileo INAV and FNAV ephemeris data is currently not valid. During this time, Hemisphere GNSS Galileo capable receivers will continue to track Galileo signals, but without a valid ephemeris, the signals are not included in the position solution.

Solution:

Once the Galileo service returns to normal and provides valid ephemeris data, Hemisphere GNSS Galileo capable receivers will return to normal operation with the available Galileo satellite solution. Please refer to the following links provided by the European Global Navigation Satellite Systems Agency for updates.

<https://www.gsc-europa.eu/news/update-on-the-availability-of-some-galileo-initial-services>

https://www.gsc-europa.eu/system/files/galileo_documents/Galileo-service-notice-02.pdf



FURTHER INFORMATION:

If you have any further questions, please contact Hemisphere GNSS technical service department at +1 (480) 348-6380. For support via email, please contact TechSupport@HGNSS.com or consult WWW.HGNSS.COM for the latest HGNSS product and software information.

This document is provided for technical support purposes only.
Please refer to the product documentation for warranty, license and
safety information associated with the product.